






Tools needed




Screwdriver




Tape measure




Pencil




Electric drill



Drill bit




Hammer







Level




Accessories



1







2



H2	H3	
20x	20x	

5







3




H9	H5	H6	
24x	2x	4x	

6

4









1x
H8




H1 16x	H2 16x	H3 16x	H9 M4x14 7x	H11 4x	H8 1x		
-----------	-----------	-----------	-------------------	-----------	----------	--	--

5








1x
H8









H1 16x	H2 16x	H3 16x	H9 M4x14 7x	H11 4x	H8 1x		
-----------	-----------	-----------	-------------------	-----------	----------	--	--



6




7



8



Assemble



Adjustable

